

GREG BELL
Lieutenant Governor

# State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

## Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	res Present During the Inspection:
Company	Vicky Miller
OGM	Steve Demczak



# **Inspection Report**

Permit Number:	C0070018		
Inspection Type:	COMPLETE		
Inspection Date:	Thursday, May 19, 2011		
Start Date/Time:	5/19/2011 12:00:00 PM		
End Date/Time:	5/19/2011 3:00:00 PM		
Last Inspection:	Wednesday, February 16, 2011		

Inspector: Steve Demczak,

Weather: Cold, 50's

InspectionID Report Number: 2762

**Types of Operations** 

Accepted by: jhelfric 6/1/2011

Permitee: CANYON FUEL COMPANY
Operator: CANYON FUEL COMPANY
Site: SOLDIER CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

#### **Current Acreages**

<b>Total Permitted</b>	6,624.64
<b>Total Disturbed</b>	24.32
Phase I	
Phase II	
Phase III	

#### Mineral Ownership

# ✓ Federal ✓ Underground ✓ State □ Surface □ County □ Loadout □ Fee □ Processing □ Other □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition: Canyon Fuel Company has just one permit condition for the Soldier Canyon Mine; to submit water quality data in an electronic format through the Electronic Data Input web site.

Permitting Actions: None

Inspector's Signature:

Steve Demozak, Wank

Date

Tuesday, MayDNR1

OIL. GAS & MINING

Inspector ID Number: 39

Permit Number: C0070018
Inspection Type: COMPLETE

Inspection Date: Thursday, May 19, 2011

Page 2 of 4

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		$\checkmark$	
2.	Signs and Markers	✓		<b>✓</b>	
3.	Topsoil	<b>~</b>		~	
4.a	Hydrologic Balance: Diversions	<b>✓</b>		<b>✓</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		~	
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>✓</b>			
4.d	Hydrologic Balance: Water Monitoring	<b>✓</b>		<b>~</b>	
4.e	Hydrologic Balance: Effluent Limitations	<b>✓</b>		~	
5.	Explosives		<b>V</b>		
6.	Disposal of Excess Spoil, Fills, Benches		<b>~</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments		<b>✓</b>		
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓		<b>~</b>	
11.	Contemporaneous Reclamation		<b>V</b>		
12.	Backfilling And Grading		<b>✓</b>		
13.	Revegetation		<b>Y</b>		
14.	Subsidence Control		<b>✓</b>		
15.	Cessation of Operations	<b>~</b>		<b>~</b>	
16.8	a Roads: Construction, Maintenance, Surfacing	✓			
16.Ł	Roads: Drainage Controls	✓		<b>✓</b>	
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations	<b>✓</b>		~	
19.	AVS Check	<b>V</b>			
20.	Air Quality Permit	<b>✓</b>			
21.	Bonding and Insurance	✓		<b>V</b>	
22.	Other				

Permit Number: C0070018
Inspection Type: COMPLETE

Inspection Date: Thursday, May 19, 2011

Page 3 of 4

# 1. Permits, Change, Transfer, Renewal, Sale

No permitting action is currently being processed with the Division for Soldier Creek Mine. The permit will expire on Feb. 12, 2012. The SPCC plan was last inspected on December 3, 2007. The UPDES permit will expire on March 31, 2011.

#### 2. Signs and Markers

The identification sign was on the side of the main road overlooking the sediment pond. The information addressed the requirements of the R645 Coal Rules.

## 3. Topsoil

The topsoil piles are located below the mine. There were no signs of wind or water erosion.

# 4.a Hydrologic Balance: Diversions

Diversions were opened and functioning as designed.

# 4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment pond contained a small amount of water. It is unlikely to discharge in the near future. I inspected the sediment pond and did not see any hazardous conditions. The permittee inspected the pond on April 19, 2011. There were no hazardous conditions reported.

# 4.d Hydrologic Balance: Water Monitoring

The site had met requirements for taking water samples in high flow year,

### 4.e Hydrologic Balance: Effluent Limitations

No discharge for the first quarter.

# 8. Noncoal Waste

The site was clear of non-coal waste material.

# 10. Slides and Other Damage

No slides or orther damage was noticed during the inspection.

# 15. Cessation of Operations

The mine site is still in temporary cessation.

#### 16.b Roads: Drainage Controls

Diversions are functioning as designed.

**Inspection Continuation Sheet** 

Permit Number: C0070018
Inspection Type: COMPLETE

Inspection Date: Thursday, May 19, 2011

Page 4 of 4

# 18. Support Facilities, Utility Installations

There are no new facilities.

# 21. Bonding and Insurance

The insurance policy will expire on July 31, 2011. The bonding amount is \$1,593,000.